

Natural avalanche hit Daisy Pass road

Daisy Pass
Cooke City
2/25/2023
Code
SS-N-R3-D2-O
Elevation
9400
Aspect
SW
Latitude
45.03980
Longitude
-109.94000
Notes

A snowmobiler saw this natural avalanche hit the Daisy Pass road within 10 minutes of riding by. He did a beacon search on the debris to confirm no one had been caught. It occurred about noon. This path is not very visible from the bottom and is not one that runs regularly. [It killed a rider who was on the road in February 2012.](#) The accident report has good photos of the path from afar.

Wind-[loading](#) in the start zone was the likely [trigger](#) since skiers and sledgers do not access it.

From an email: "The crown was hard to see, but only looked a few feet deep where I could see it, but the debris pile was 10'+ on the road."

A big thanks to Dan Wykoff for providing the story and pictures.

Number of slides
1
Number caught
0
Number buried
0
Avalanche Type
Soft slab avalanche
Trigger
Natural trigger
R size
3
D size
2
Bed Surface
O - Old snow
Problem Type
Persistent Weak Layer
Vertical Fall
700ft

Slab Width

200.00ft

Images

[Natural avalanche hit Daisy Pass road_5](#)

[Natural avalanche hit Daisy Pass road_4](#)

[Natural avalanche hit Daisy Pass road_3](#)

[Natural avalanche hit Daisy Pass road_2](#)

[Natural avalanche hit Daisy Pass road_1](#)

Snow Observation Source

[Natural avalanche hit Daisy Pass road](#)

Slab Thickness units

centimeters

Single / Multiple / Red Flag

Single Avalanche

Advisory Year

[22-23](#)